

Quality Hot Spot Training Sheet
Careful Gypsum Stocking and Storage



**Gypsum stocked incorrectly
on edge**



**Gypsum stocked correctly
flat and in center of room,
maximum of 25 boards high**

Training emphasis:

Proper stocking of gypsum to avoid structural damage to house.

Reference: US Gypsum Product information: Storage and Handling
“Gypsum Association literature states unequivocally that board should be stacked flat because stacking boards vertically against a wall poses a safety hazard.” . . . and . . . “a stack of only 25 boards weighs over a ton.”

(Demonstrate at jobsite with our gypsum supplier and our hanging crew)

Training Session: Date: _____ Time: _____

Job Location: _____

List of Attendees: